

OCCURRENCE REPORT: 64034

Flight Safety incident reports are produced under the authority of the Minister of National Defence (MND) pursuant to Section 4.2 of the Aeronautics Act (AA), AND in accordance with A-GA-135-001/AA-001, Flight Safety FOR the Canadian Forces. They are prepared solely FOR the purpose of accident prevention AND shall not be used FOR legal, administrative OR disciplinary action.

FSIS 64034 29 MAR 1963 AIR ACCIDENT

Status: supplemental sent

Unclassified

1. Injury Level: No Injury

2. Aircraft/Operated By: CC130303

3. Aircraft Ownership: 435 SQN / 17 WING / 3435 /

4. A. Location:

Latitude: N63-59

Longitude: W022-37

4. B. Date/Time: 290000Z MAR 1963

4. C. Phase of Flight: LANDING - FINAL APPROACH (1 MILE TO FLARE)

5. Damage Level: Serious - Major component / 3rd line maint

7. Mission Type: TRANSPORT AND COMMUNICATIONS, TALEX (INCLUDES HELOS)

8. Description: - ON FINAL APPROACH, A PORTION OF A BLADE DE-ICER HEATER CUFF AND PART OF THE HEATER (#3 PROP) SEPARATED FROM THE BLADE AND STRUCK THE ICE PROTECTOR SHIELD ON THE STBD SIDE OF THE FUSELAGE CAUSING SLIGHT DAMAGE.

22. A. Investigation: SEVERE VIBRATION WAS FELT AND OVERSHOOT ACTION TAKEN. NUMBER 3 ENGINE WAS OBSERVED TO BE VIBRATING AND WAS FEATHERED. THE CAUSE IS UNDETERMINED.

23. Cause Factors: UNDETERMINED