OCCURRENCE REPORT: 67633

Flight Safety incident reports are produced under the authority of the Minister of National Defence (MND) pursuant to Section 4.2 of the Aeronautics Act (AA), AND in accordance with A-GA-135-001/AA-001, Flight Safety FOR the Canadian Forces. They are prepared solely FOR the purpose of accident prevention AND shall not be used FOR legal, administrative OR disciplinary action.

FSIS 67633 11 MAR 1982 GROUND ACCIDENT

Status: supplemental sent

TR 474 12/MAR/1982 14:00

Unclassified

1. Injury Level: No Injury

2. Aircraft/Operated By: CC130310

3. Aircraft Ownership: 429 SON / 2587 / 8 WG /

4. A. Location: - TRENTON -

Latitude: N44-7 Longitude: W077-32

4. B. Date/Time: 111400Z MAR 1982

4. C. Phase of Flight: MAINTENANCE - MAINT (2ND AND/OR 3RD LINE)

5. Damage Level: Serious - Major component / 3rd line maint

8. Description: WHILE PERFORMING A RETRACTION TEST THE AC NOSE SCISSORS WERE LEFT UNDONE.

13. Flight/Ground Conditions: OUTDOOR FLIGHTLINE - WINTER

22. A. Investigation: THE LOWER SCISSOR PUNCTURED THE PRESSURE DIAPHRAGM AREA OF THE NOSE BAY.

23. Cause Factors: PERSONNEL SUPERVISION/UNIT INATTENTION *** FINDINGS ***

MAINTENANCE FAILED TO CONNECT THE NOSE SCISSORS BEFORE RETRACTION WAS CARRIED OUT. SUPERVISOR FAILED TO ENSURE THAT THE AIRCRAFT WAS PROPERLY PREPARED BEFORE RETRACTION CARRIED OUT.

PERSONNEL MAINTENANCE/CANADIAN FORCES INATTENTION *** FINDINGS ***

MAINTENANCE FAILED TO CONNECT THE NOSE SCISSORS BEFORE RETRACTION WAS CARRIED OUT. SUPERVISOR FAILED TO ENSURE THAT THE AIRCRAFT WAS PROPERLY PREPARED BEFORE RETRACTION CARRIED OUT.

ALL

24. Preventive Measures: (SEE DETAILED DESCRIPTION) *** PREVENTIVE MEASURES ***
PERSONNEL HAVE BEEN MADE AWARE OF THE POTENTIAL HAZARD INVOLVED WHEN DOING RETRACTION TESTS.