## **OCCURRENCE REPORT: 65322**

Flight Safety incident reports are produced under the authority of the Minister of National Defence (MND) pursuant to Section 4.2 of the Aeronautics Act (AA), AND in accordance with A-GA-135-001/AA-001, Flight Safety FOR the Canadian Forces. They are prepared solely FOR the purpose of accident prevention AND shall not be used FOR legal, administrative OR disciplinary action.

FSIS 65322 19 AUG 1972 GROUND ACCIDENT

Status: supplemental sent

## Unclassified

1. Injury Level: No Injury

2. Aircraft/Operated By: CC130313

3. Aircraft Ownership: 435 SQN / 17 WING / 3435 /

4. A. Location: Latitude: N46-7 Longitude: W064-41

4. B. Date/Time: 191900Z AUG 1972

4. C. Phase of Flight: LOAD/UNLOADING - CARGO HANDLING5. Damage Level: Serious - Major component / 3rd line maint

7. Mission Type: AIR SHOWS/PRACTICES/DISPLAY

**8. Description**: - WHILE LOADING A BULLDOZER AFTER COMPLETING THE LAPES AIRDROP DEMONSTRATION, THE BULLDOZER SWUNG RIGHT AS IT CROSSED THE THRESHOLD OF THE AC FLOOR AT THE

TOP OF THE RAMP, OWING TO UNEVEN ALIGNMENT OF THE CLEATS ON THE RIGHT AND LEFT TRACKS.

13. Flight/Ground Conditions: INSIDE A/C (LOADING A/C)

22. A. Investigation: PORTIONS OF THE MACHINE STRUCK THE RH INNER WHEEL WELL CAUSING STRUCTURAL DAMAGE TO THE PRESSURE BULK- HEAD AND LESSER DAMAGE TO THE RIGHT REAR MAIN L/G TRACK AND REFUELLING MANIFOLD. INSUFFICIENT LOADING EOPT WAS PROVIDED TO SUPPORT THE

LOADING OF A LARGE TRACKED-VEHICLE IN A CONFINED AIRCRAFT AREA.

23. Cause Factors: PERSONNEL MANAGEMENT/CHQ RESOURCES